



Limited Asbestos and Lead Paint Sampling Report

Sycamore Canyon Elementary School Santee School District

4/16/19

Requested Sampling Areas:

Old Admin Building, Covered Walkways
Relocatable Buildings: P1, P2,

General Information

Owner:

Santee School District
9619 Cuyamaca Street, Santee, CA 92071

Report Prepared / Reviewed By:

David Christy
WEST - Sr. Partner
Certified Asbestos Consultant 92-0703



Asbestos Sampling Report - Table of Contents

Executive Summary	3
Asbestos Inspection – General Information	3
Asbestos Building Inspection Findings	3
Inspection Findings	4
Survey Methodology	7
Asbestos Bulk Sampling Strategy	7
Sampling Method / Bulk Sampling	7
Asbestos Bulk Sample Analysis	7
Deviations in Sample Results	7
Lead Paint / Ceramic Tiles	8
Definitions	8
General Limitations	9
Detailed Asbestos Sampling Breakdown	8-12

Attachment One - Asbestos Laboratory Sheets & Chains of Custodies

Attachment Two – Limited Lead Based Paint Sampling Report

Executive Summary

Sampling Date:	4/16/19, 5/1/19 (Limited Asbestos Sampling) 4/16/19 (Limited Lead Paint Sampling)
Survey Description:	Old Admin Building, Covered Walkways Relocatable Buildings: P1, P2 Interior and Exteriors (limited sampling)
Sampling Scope:	As requested by owner and listed within accepted WEST proposal and agreement Including: Limited accessible sampling – Interiors and Exteriors
Services Complete:	Conduct a limited (non-destructive) asbestos inspection, laboratory Analysis, reporting as listed above of areas. Conduct limited XRF lead paint sampling.
Laboratory Analysis:	EMSL Analytical, San Diego, Ca. NVLAP and California Accredited Laboratory to provide: “Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy (PLM)
On-site Sampling:	David Christy, a State of California Certified Asbestos Consultant (92-0703)
Additional Sampling:	Lead Paint Testing (XRF Sampling) Completed by Allstate Services (report attached)
General Warrantee:	WEST warrants the findings and conclusions contained herein have been promulgated in accordance with generally accepted asbestos inspection and evaluation methods for the referenced site.
Access Note:	WEST was given limited access for areas outlined for sampling within the scope of inspection.

Asbestos Inspection – General Information

Any suspect building materials encountered by WEST during the asbestos inspection, found within the specific areas called out for inspection / sampling, were collected and analyzed for the presence of asbestos. The samples of the various building materials that were collected were analyzed using polarized light microscopy (PLM). A breakdown of laboratory analysis for each asbestos sample collected is included in the attached report. If any material containing asbestos will be disturbed, appropriate local, state, and federal regulations and guidelines must be followed.

WEST collected samples of suspect building materials that were accessible at the time of the inspection as found and noted by the on-site inspector. WEST utilized EMSL Analytical located in San Diego, California, a NVLAP and California DHS Accredited Laboratory to provide: “Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy (PLM). WEST warrants that the findings and conclusions contained herein have been promulgated in accordance with generally accepted asbestos hazard evaluation methods for the site referenced in this report.

Asbestos Building Inspection Findings

Based on the above collected information and the sample analysis attached to this report, asbestos was found as part of the asbestos inspections (ACM, ACBM).

There are assumptions made within this sampling report grouping similar building materials with similar age and appearance together for means of building material identification and grouping for sampling. This should also be followed while conducting asbestos removal of these materials. If any building material is discovered to be suspect of containing asbestos, and it was not accessible or identified in this building inspection report, additional samples should be collected and analyzed and the building inspection report and data should subsequently be updated. California Code of Regulations Title 8, Section 1529 states that asbestos containing material and presumed asbestos containing material that will be disturbed during demolition, construction, renovation, etc. must be handled according to the standard. The state of California states that a material that contains one-tenth of one percent asbestos is classified as a regulated asbestos material. **Additional investigation and sampling are recommended if any newly discovered building material is identified that is not called out within this asbestos sampling report.**



Materials discovered to contain asbestos (known and assumed – asbestos and lead paint)

Asbestos Exterior Stucco Material – Old Admin Building (<1% Chrysotile) – ACM,
Assumed greater than 1% asbestos until point count analysis has proven otherwise.
(assume all exterior wall stucco is asbestos containing)

Asbestos Exterior Stucco Ceiling Material – Underside of Covered Walkways (<1% Chrysotile) – ACM,
Assumed greater than 1% asbestos until point count analysis has proven otherwise.
(assume all exterior wall stucco is asbestos containing)

Asbestos Floor Tile (9x9) – (3% - 4% Chrysotile) – ACBM,
(found within the old Admin Building)
(all areas of the building – assume all 9x9 floor tile throughout the building is asbestos containing)

Asbestos Interior Wall Plaster Material – (<1% Chrysotile) – ACBM,
Assumed greater than 1% asbestos until point count analysis has proven otherwise.
(found within the Old Admin Building - assume all plasters throughout the building are asbestos containing)

Asbestos Drywall Joint Compound Material – (2% Chrysotile) – ACBM,
(found within the Old Admin Building - assume all Drywall Joint Compound throughout the building is asbestos containing)

Assumed: All Building materials not sampled within this sampling report (undiscovered building materials -or- building materials outside of the sampling scope of work)

Any building materials not listed within this sampling report for the referenced locations, whether outside sampling scope of work or newly discovered, shall be assumed to be asbestos containing greater than 1%. Additional investigation and sampling are recommended for these types of unreported materials. Asbestos bulk sampling and inspection services must be completed by State of California Certified personnel (Site Surveillance Technician or Certified asbestos Consultant). All laboratory analysis and reporting must be completed by a licensed and certified laboratory facility.

Lead Paint: Lead Paint was not discovered based on XRF sampling conducted by Allstate Services.
(All sinks, toilets and fountains are known or assumed to be lead containing from the entire permanent build)

Special Notation:

At the time of the survey, only specific building materials were called out for asbestos bulk sampling within the buildings listed within this sampling report. The site was active with staff the day of the on-site inspection, and was conducted during normal hours (during spring break) WEST was limited to the type and location of samples collected. The sampling as completed was **non destructive sampling** relating to asbestos bulk sampling from concealed areas and above ceilings / ceiling tiles within the building surveyed since the building was soon to be occupied and functional (functioning school building) after spring break. Samples were collected to the best of the inspector’s ability and access while causing minimum disturbance to surrounding areas. Only bulk sampling of exposed and accessible building materials from areas granted access and part of the asbestos sampling scope of work were completed.

Survey Methodology

The sampling as completed included **non destructive sampling** to conduct asbestos bulk sampling from concealed areas and above ceilings / ceiling tiles within the building surveyed since the buildings were partially occupied and functional. (functioning buildings, to resume school activities the following week – all on-site sampling conducted when school was on spring break. Samples were collected to the best of the inspector’s ability and access. There are assumptions made within this sampling report as it relates to building materials not accessible at the time of the inspections. Sampling of these areas was conducted at access points that were previously in place or in direct view of the on-site inspector. The surveyor proceeded to complete a visual inspection of the surrounding surfaces and the building components that were found at the building site as part of the asbestos sampling. Following the review of each inspection location that was remaining at the time of the inspection, the surveyor then made inspection notes while still in the field. These notes recorded data on the presence, type and general condition of any suspected ACMs encountered, and on a system-by-system basis as outlined in this report. The sampling analysis breakdowns are provided in this report.

Asbestos Bulk Sampling Strategy

The collection of bulk samples was performed in sufficient frequency to obtain only a basic pattern as to the use of possible asbestos containing materials (ACM) and asbestos containing building materials (ACBM) with in the limited areas of the buildings / areas called out for inspections. It is known however, that inconsistencies within construction or later repair or renovation may result in deviation from this general pattern. For this reason, it is not possible to positively identify the presence and extent of asbestos building materials associated with the areas sampled without inspecting and sampling every square foot of all building surfaces and components encountered during the inspection process. As this was outside of the scope of this assignment, identification of asbestos-suspect materials was based on the surveyor's own experience and knowledge of the use of asbestos in buildings, the age, and the general appearance of the materials encountered. A complete list of sampled materials is attached to this report.

Sampling Method – Bulk Sampling

Wherever the collection of a bulk sample became necessary, samples were collected using general hand tools and placed in plastic zip bags, which were individually labelled with a sample number and description of the sampling location. This information was also recorded on a transmittal form. One copy of this form remained with the samples when transported to the laboratory. The second copy was retained by the surveyor. Care was used by the surveyor (wherever possible) to collect samples at a location which produced the least visual impact or would be least objectionable to building occupants.

Asbestos Bulk Sample Analysis

Each of the bulk samples collected were analysed by EMSL Analytical located in San Diego, California, using a combination of dispersion staining and polarized light microscopy. Sample preparation and analytical procedures follow the protocol outlined for NIOSH Method 9002 for bulk asbestos analysis, and the US EPA Method 600/R-93/116 dated July, 1993. Each of these methods is recognized by both federal and provincial authorities. For quality control purposes, the laboratory used for the sample asbestos analysis is certified under the National Voluntary Laboratory Accreditation Program (NVLAP) to perform asbestos analysis of bulk samples.

Deviations in Sample Results

Due to the removal and replacement of individual building materials over the course of a building's life or due to the installation of visually similar building products, it is possible that individual building surfaces may not be characteristic of the samples collected. Every effort was made to collect samples from typical building materials and components as found during the on-site sample collection. If any building material is discovered to be suspect of containing asbestos, and it was not accessible or identified in this building inspection report, additional samples should be collected and analyzed and the building inspection report and data should subsequently be updated.

Lead Paint / Lead Ceramic Tile

CAL-OSHA Regulations (Title 8 CCR Section 1532.1 and 29 CFR 1926.62) apply to all construction work where an employee may be occupationally exposed to lead, and therefore may be applicable to renovation or demolition projects involving paints with any concentration of lead. When conducting construction activities, **which disturb lead in any amount or create an exposure to workers**, the employer is required to provide worker protection and conduct exposure assessments. All California employers should consult Cal-OSHA Regulations at Title 8, 1532.1, “Lead in Construction” standards for complete requirements.

Since the building listed above is undergoing renovation / demolition, **all construction personnel** performing the construction work should be properly trained in lead-related construction. California regulations define lead-related construction work as, “Construction, alteration, painting, demolition, salvage, renovation, repair, or maintenance of any residential, public or commercial building, including preparation and cleanup, which, by using or disturbing lead containing material or soil, may result in significant exposure of individuals to lead.”

To also protect against this risk of lead exposure, on April 22, 2008, EPA issued the [Renovation, Repair and Painting Rule](#). It requires that firms performing renovation, repair, and painting projects that disturb lead-based paint in pre-1978 homes, child care facilities and **schools** be certified by EPA and that they use certified renovators who are trained by EPA-approved training providers to follow lead-safe work practices. Individuals can become certified renovators by taking an eight-hour training course from an EPA-approved training provider.

Lead based paint (LBP) sampling and identification was conducted as part of this scope of work.

Definitions of ACM

Asbestos Containing Material (ACM):

According to EPA, OSHA and Cal-OSHA, asbestos containing material is a material that has greater than 1% asbestos.

Asbestos Containing Building Material (ACBM):

For purposes of AHERA, material with greater than 1% asbestos that was used on the interior construction of a school is called asbestos containing building material (ACBM).

Asbestos Containing Construction Material (ACCM):

According to Title 8, Section 1529, asbestos containing construction material means any manufactured construction material which contains more than 0.1 % asbestos by weight.

Presumed Asbestos Containing Material (PACM):

Any thermal system insulation and surfacing material found in buildings constructed no later than 1980. The designation of a material as PACM may be rebutted pursuant to Title 8, section 1529, subsection (k)(5).

Regulated Asbestos Containing Material (RACM):

The EPA in the National Emission Standard for Hazardous Air Pollutants (NESHAP) defines RACM as (a) Friable asbestos containing material, (b) Category I non-friable asbestos containing material that has become friable, (c) Category I non-friable asbestos containing material that will be or has been subjected to sanding, grinding, cutting or abrading, or (d) Category II non-friable asbestos containing material that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material in the course of demolition or renovation operations regulated by Subpart M.

General Limitations

The survey as completed was of sufficient depth to provide a screening for the purpose of establishing the presence of asbestos containing materials (ACM) within the limited areas inspected within the building. Due to the nature of building construction some limitations exist as to the possible extent and accuracy of this survey. Such limitations include any inconsistencies in the use of materials during construction or later repairs or renovations that result in deviations from the general pattern. However, without sampling every square foot of building materials, it is not possible to rule out such limitations.

As this is not a practical approach to sample every square foot of building material, the survey was completed based on the collection of a sufficient number of samples representing the building materials listed in this sampling report and visually encountered. Every effort was made to collect these samples from typical or representative materials as they were encountered.

The collection of data, quantification of any damage, and confirmation of existing conditions, is limited by the surveyor's ability to access and visually inspect conditions at each inspection location. The collection of data above fixed or mechanically fastened ceilings, or from within concealed cavities or shafts, is therefore limited by the availability and location of access points, hatches, etc. Areas that were not accessed include but not limited to inside wall cavities, above ceilings, above fixed ceiling tiles, areas behind security fences, areas behind security covered windows, and non-exposed mechanical equipment.

The survey, as completed, did not include demolition and dismantlement of equipment and building materials. The sampling was conducted to the best ability and safety of the on-site inspectors on-site.

The field observations, measurements, and analysis are considered sufficient in detail and scope to form a reasonable basis for asbestos containing materials (ACM) overview of the buildings in question as it relates to the building systems. Western Environmental & Safety Technologies LLC (WEST) warrants that the findings and conclusions contained herein have been promulgated in accordance with generally accepted asbestos hazard evaluation methods, for the site referenced in this report.

These evaluation methods have been developed to provide the client with information regarding apparent indications of existing or potentially hazardous asbestos conditions relating to the property and are necessarily limited to the conditions observed and information available at the time of the site visit and research. There is a distinct possibility that conditions may exist which could not be reasonably identified within the scope of the assessment or which were not apparent during the site visit.

Western Environmental & Safety Technologies LLC (WEST) believes that the information collected during the survey period concerning this property is reliable. However, Western Environmental & Safety Technologies LLC (WEST) cannot warrant or guarantee that the information provided is absolutely complete or accurate beyond the current asbestos consulting industry standards.

The conclusions and recommendations presented in this report are based upon reasonable visual inspection, site investigation, and bulk sampling of the property and research of available materials within the scope and budget of the contract. The information presented is relevant to the dates of our site visit and should not be relied upon to represent conditions at later dates. The opinions expressed herein are based on information obtained during our on-site inspection efforts and on our experience. If additional information becomes available, we request the opportunity to review the information and modify our opinions, if necessary.

Our services have been provided using that degree of care and skill ordinarily exercised, under similar circumstances, by environmental consultants practicing in this or similar localities. No other warranty, expressed or implied, is made as to the professional opinions presented in this report. Western Environmental & Safety Technologies LLC (WEST) is not responsible for the conclusions, opinions, or recommendations made by others based on this information.

Report Prepared By and Laboratory Sample Analysis Reviewed By:



5/15/19

David Christy
 Certified Asbestos Consultant - CAC# 92-0703
 ☎ Tel: (858) 271-1842 (office)
 ☎ Tel: (619) 571-3987 (cell)
 📠 FAX: (858) 271-1856
 ✉ Email: gowestdc@msn.com

Review Dates

Limited Asbestos Sampling as Requested
Sycamore Canyon Elementary School (limited buildings / sampling areas)
Asbestos Bulk Sampling Breakdown

Sample #	Sample Date	Area	Sample Location	Material Sampled	Results
01	4/16/19	P2	Roof	Metal Roof Seam Seal	None Detected
02	4/16/19	P1-P2	Roof	Metal Roof Seam Seal	None Detected
03	4/16/19	P1	Roof	Metal Roof Seam Seal	None Detected
04	4/16/19	P1-P2	Exterior – South	Rubberized base at concrete	None Detected
05	4/16/19	P1-P2	Exterior – Mid	Rubberized base at concrete	None Detected
06	4/16/19	P1-P2	Exterior – North	Rubberized base at concrete	None Detected
07	4/16/19	P1-P2	Exterior – South	Concrete Slab	None Detected
08	4/16/19	P1-P2	Exterior – Mid	Concrete Slab	None Detected
09	4/16/19	P1-P2	Exterior – North	Concrete Slab	None Detected
10SF	4/16/19	P1	Interior	Sheet Floor	None Detected
10M	4/16/19	P1	Interior	Sheet Floor Mastic	None Detected
11	4/16/19	P1	Interior	Sheet Floor Core	None Detected
12	4/16/19	P2	Interior	Sheet Floor Core	None Detected
13	4/16/19	P1	Interior	Carpet Glue	None Detected
14	4/16/19	P1	Interior	Carpet Glue	None Detected
15	4/16/19	P2	Interior	Carpet Glue	None Detected
16	4/16/19	P1	Interior	Cove Base Mastic	None Detected
17	4/16/19	P2	Interior	Cove Base Mastic	None Detected
18	4/16/19	P2	Interior	Cove Base Mastic	None Detected
19	4/16/19	P2	Interior	Celotex Wall Core	None Detected
20	4/16/19	P1	Interior	Drywall Wall Core behind Celotex	None Detected
21	4/16/19	P1	Interior	Drywall Wall Core behind Celotex	None Detected
22	4/16/19	P2	Interior	Drywall Wall Core behind Celotex	None Detected
23	4/16/19	P1	Interior	2x4 Ceiling Tiles (fiber glass backed)	None Detected

None Detected = No asbestos found in the sample analyzed

The sample descriptions listed above represent the location of the individual sample collected. The building material that has been sampled as listed above may be present in other locations of the building and has been represented above as a homogeneous space.

Asbestos results are reported in % using Polarized Light Microscopy (PLM) as reported by EMSL, San Diego, California.

WEST utilized EMSL located in San Diego, California. a NVLAP and California DHS Accredited Laboratory to provide: “Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy (PLM).

Limited Asbestos Sampling as Requested Sycamore Canyon Elementary School (limited buildings / sampling areas) Asbestos Bulk Sampling Breakdown					
Sample #	Sample Date	Area	Sample Location	Material Sampled	Results
24	4/16/19	P2	Interior	2x4 Ceiling Tiles (fiber glass backed)	
25	4/16/19	Old Admin	Roof – East	Roof Penetration Mastic	None Detected
26	4/16/19	Old Admin	Roof – Center	Roof Penetration Mastic	None Detected
27	4/16/19	Old Admin	Roof – West	Roof Penetration Mastic	None Detected
28	4/16/19	Old Admin	Roof – North	Roof Edge Mastic	None Detected
29	4/16/19	Old Admin	Roof – West	Roof Edge Mastic	None Detected
30	4/16/19	Old Admin	Roof – East	Roofing Core	None Detected
31R	4/16/19	Old Admin	Roof – West	Roofing Core (roofing)	None Detected
31P	4/16/19	Old Admin	Roof – West	Roofing Core (paper)	None Detected
32FC	4/16/19	Old Admin	Ext. Covered Walkway – E	Ceiling Stucco Core (finish coat)	<1% Chrysotile
32BC	4/16/19	Old Admin	Ext. Covered Walkway – E	Ceiling Stucco Core (base coat)	None Detected
33FC	4/16/19	Old Admin	Ext. Covered Walkway – C	Ceiling Stucco Core (finish coat)	None Detected
33BC	4/16/19	Old Admin	Ext. Covered Walkway – C	Ceiling Stucco Core (base coat)	None Detected
34FC	4/16/19	Old Admin	Ext. Covered Walkway – W	Ceiling Stucco Core (finish coat)	<1% Chrysotile
34BC	4/16/19	Old Admin	Ext. Covered Walkway – W	Ceiling Stucco Core (base coat)	None Detected
35FC	4/16/19	Old Admin	Exterior Wall – South	Wall Stucco Core (finish coat)	None Detected
35BC	4/16/19	Old Admin	Exterior Wall – South	Wall Stucco Core (base coat)	None Detected
36FC1	4/16/19	Old Admin	Exterior Wall – East	Wall Stucco Core (finish coat 1)	None Detected
36FC2	4/16/19	Old Admin	Exterior Wall – East	Wall Stucco Core (finish coat 2)	<1% Chrysotile
36BC	4/16/19	Old Admin	Exterior Wall – East	Wall Stucco Core (base coat)	None Detected
37FC	4/16/19	Old Admin	Exterior Wall – North	Wall Stucco Core (finish coat)	<1% Chrysotile
37BC	4/16/19	Old Admin	Exterior Wall – North	Wall Stucco Core (base coat)	None Detected
38CB	4/16/19	Old Admin	Interior – Northeast	Cove Base	None Detected
38M	4/16/19	Old Admin	Interior – Northeast	Cove Base Mastic	None Detected

None Detected = No asbestos found in the sample analyzed
 The sample descriptions listed above represent the location of the individual sample collected. The building material that has been sampled as listed above may be present in other locations of the building and has been represented above as a homogeneous space.
 Asbestos results are reported in % using Polarized Light Microscopy (PLM) as reported by EMSL, San Diego, California.
 WEST utilized EMSL located in San Diego, California. a NVLAP and California DHS Accredited Laboratory to provide: “Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy (PLM).”



Limited Asbestos Sampling as Requested
Sycamore Canyon Elementary School (limited buildings / sampling areas)
Asbestos Bulk Sampling Breakdown

Sample #	Sample Date	Area	Sample Location	Material Sampled	Results
39CB	4/16/19	Old Admin	Interior – South	Cove Base	None Detected
39M	4/16/19	Old Admin	Interior – South	Cove Base Mastic	None Detected
40CB	4/16/19	Old Admin	Interior – Center	Cove Base	None Detected
40M	4/16/19	Old Admin	Interior – Center	Cove Base Mastic	None Detected
41FT	4/16/19	Old Admin	Interior – Restroom	9x9 Floor Tile	3% Chrysotile
41M	4/16/19	Old Admin	Interior – Restroom	Floor Tile Mastic	None Detected
42FT	4/16/19	Old Admin	Interior – Restroom	9x9 Floor Tile	3% Chrysotile
42M	4/16/19	Old Admin	Interior – Restroom	Floor Tile Mastic	None Detected
43FT	4/16/19	Old Admin	Interior – Closet	9x9 Floor Tile	4% Chrysotile
43M	4/16/19	Old Admin	Interior – Closet	Floor Tile Mastic	None Detected
44	4/16/19	Old Admin	Interior – West	2x4 Ceiling Tiles	None Detected
45	4/16/19	Old Admin	Interior – Center	2x4 Ceiling Tiles	None Detected
46	4/16/19	Old Admin	Interior – Northeast	2x4 Ceiling Tiles	None Detected
47	4/16/19	Old Admin	Interior – North	12x12 Ceiling Tiles	None Detected
48	4/16/19	Old Admin	Interior – West	12x12 Ceiling Tiles	None Detected
49	4/16/19	Old Admin	Interior – West	12x12 Ceiling Tiles	None Detected
50SC	4/16/19	Old Admin	Interior – West Closet	Wall Plaster Core (skim coat)	<1% Chrysotile
50P	4/16/19	Old Admin	Interior – West Closet	Wall Plaster Core (plaster)	None Detected
51SC	4/16/19	Old Admin	Interior – Restroom	Wall Plaster Core (skim coat)	<1% Chrysotile
51P	4/16/19	Old Admin	Interior – Restroom	Wall Plaster Core (plaster)	None Detected
52	4/16/19	Old Admin	Interior – East	Wall Plaster Core	None Detected
53T	4/16/19	Old Admin	Interior – South	Wall Plaster Core (texture)	None Detected
53SC	4/16/19	Old Admin	Interior – South	Wall Plaster Core (skim coat)	<1% Chrysotile
54	4/16/19	Old Admin	Interior – Art Room	24x24 wall tile	None Detected

None Detected = No asbestos found in the sample analyzed

The sample descriptions listed above represent the location of the individual sample collected. The building material that has been sampled as listed above may be present in other locations of the building and has been represented above as a homogeneous space.

Asbestos results are reported in % using Polarized Light Microscopy (PLM) as reported by EMSL, San Diego, California.

WEST utilized EMSL located in San Diego, California, a NVLAP and California DHS Accredited Laboratory to provide: “Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy (PLM).”



Limited Asbestos Sampling as Requested Sycamore Canyon Elementary School (limited buildings / sampling areas) Asbestos Bulk Sampling Breakdown					
Sample #	Sample Date	Area	Sample Location	Material Sampled	Results
55	4/16/19	Old Admin	Interior – Art Room	Wall Tile Glue	None Detected
56	4/16/19	Old Admin	Interior – Art Room	24x24 wall tile	None Detected
57	4/16/19	Old Admin	Interior – Art Room	Wall Tile Glue	None Detected
58	4/16/19	Old Admin	Int – Rear old mech. room	HVAC Duct Tape	None Detected
59SP	4/16/19	Old Admin	Int – Rear old mech. room	HVAC Duct Tape (silver paint)	None Detected
59W	4/16/19	Old Admin	Int – Rear old mech. room	HVAC Duct Tape (wrap)	None Detected
60SP	4/16/19	Old Admin	Int – Rear old mech. room	HVAC Duct Tape (silver paint)	None Detected
60W	4/16/19	Old Admin	Int – Rear old mech. room	HVAC Duct Tape (wrap)	None Detected
61	4/16/19	Old Admin	Int – Rear old mech. room	Wall Tile Mastic	None Detected
62	4/16/19	Old Admin	Int – Rear old mech. room	Wall Tile Mastic	None Detected
63	4/16/19	Old Admin	Int – Rear old mech. room	Wall Tile Mastic	None Detected
64M	4/16/19	Old Admin	Int – Rear old mech. room	Black Wall Mastic	None Detected
64SC	4/16/19	Old Admin	Int – Rear old mech. room	Plaster skim coat	<1% Chrysotile
64P	4/16/19	Old Admin	Int – Rear old mech. room	Plaster	None Detected
65M	4/16/19	Old Admin	Int – Rear old mech. room	Black Wall Mastic	None Detected
65SC	4/16/19	Old Admin	Int – Rear old mech. room	Plaster skim coat	<1% Chrysotile
65P	4/16/19	Old Admin	Int – Rear old mech. room	Plaster	None Detected
66	4/16/19	Old Admin	Int – Rear old mech. room	12x12 wall tile	None Detected
67DW	4/16/19	Old Admin	Int – Rear old mech. room	Drywall Ceiling Core (drywall)	None Detected
67JC	4/16/19	Old Admin	Int – Rear old mech. room	Drywall Ceiling Core (joint comp)	2% Chrysotile
68DW	4/16/19	Old Admin	Int – Rear old mech. room	Drywall Ceiling Core (drywall)	None Detected
68JC	4/16/19	Old Admin	Int – Rear old mech. room	Drywall Ceiling Core (joint comp)	2% Chrysotile
69DW	4/16/19	Old Admin	Int – Rear old mech. room	Drywall Ceiling Core (drywall)	None Detected
69JC	4/16/19	Old Admin	Int – Rear old mech. room	Drywall Ceiling Core (joint comp)	2% Chrysotile

None Detected = No asbestos found in the sample analyzed
 The sample descriptions listed above represent the location of the individual sample collected. The building material that has been sampled as listed above may be present in other locations of the building and has been represented above as a homogeneous space.
 Asbestos results are reported in % using Polarized Light Microscopy (PLM) as reported by EMSL, San Diego, California.
 WEST utilized EMSL located in San Diego, California. a NVLAP and California DHS Accredited Laboratory to provide: “Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy (PLM).”



Limited Asbestos Sampling as Requested Sycamore Canyon Elementary School (limited buildings / sampling areas) Asbestos Bulk Sampling Breakdown					
Sample #	Sample Date	Area	Sample Location	Material Sampled	Results
70	4/16/19	P1-P2	P1 exterior	Wood Trim Window Caulking	None Detected
71	4/16/19	P1-P2	P2 Exterior	Wood Trim Window Caulking	

None Detected = No asbestos found in the sample analyzed
 The sample descriptions listed above represent the location of the individual sample collected. The building material that has been sampled as listed above may be present in other locations of the building and has been represented above as a homogeneous space.
 Asbestos results are reported in % using Polarized Light Microscopy (PLM) as reported by EMSL, San Diego, California.
 WEST utilized EMSL located in San Diego, California. a NVLAP and California DHS Accredited Laboratory to provide: “Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy (PLM).”



WESTERN ENVIRONMENTAL & SAFETY TECHNOLOGIES LLC

“an environmental consulting firm”

Attachment One

Asbestos Laboratory Sheets & Chain of Custody's



EMSL Analytical, Inc.

7916 Convoy Court, Building 4, Suite A San Diego, CA 92111

Tel/Fax: (858) 499-1303 / (858) 499-1304

<http://www.EMSL.com> / sandiegolab@emsl.com

EMSL Order: 431903661

Customer ID: WEST60

Customer PO:

Project ID:

Attention: David A Christy
Western Environmental & Safety Tech.
7676 Hazard Center Drive
Suite 500
San Diego, CA 92108

Phone: (619) 571-3987

Fax: (858) 271-1856

Received Date: 04/17/2019 10:40 AM

Analysis Date: 05/01/2019

Collected Date:

Project: SYCAMORE E.S. - SANTEE, CA

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
01 431903661-0001	PROJECT SAFE RELO - P-2 ROOF - METAL ROOF SEAM SEAL	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
02 431903661-0002	PROJECT SAFE RELO - P-1-P-2 ROOF - METAL ROOF SEAM SEAL	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
03 431903661-0003	PROJECT SAFE RELO - P-1 ROOF - METAL ROOF SEAM SEAL	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
04 431903661-0004	PROJECT SAFE RELO - P-1-P2 EXT. S. - RUBBER BASE @ CONCRETE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
05 431903661-0005	PROJECT SAFE RELO - P-1-P2 EXT. M. - RUBBER BASE @ CONCRETE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
06 431903661-0006	PROJECT SAFE RELO - P-1-P2 EXT. N. - RUBBER BASE @ CONCRETE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07 431903661-0007	PROJECT SAFE RELO - P1-P2 EXT. S - CONCRETE SLAB	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
08 431903661-0008	PROJECT SAFE RELO - P1-P2 EXT. M - CONCRETE SLAB	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09 431903661-0009	PROJECT SAFE RELO - P1-P2 EXT. N - CONCRETE SLAB	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
10-Sheet Flooring 431903661-0010	PROJECT SAFE RELO - P1 INT. - SHEET FLOOR CORE	Gray Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
10-Mastic 431903661-0010A	PROJECT SAFE RELO - P1 INT. - SHEET FLOOR CORE	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
11 431903661-0011	PROJECT SAFE RELO - P1 INT. - SHEET FLOOR CORE	Gray Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
12 431903661-0012	PROJECT SAFE RELO - P2 INT. - SHEET FLOOR CORE	Gray Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected

Initial report from: 05/01/2019 23:20:01



EMSL Analytical, Inc.

7916 Convoy Court, Building 4, Suite A San Diego, CA 92111

Tel/Fax: (858) 499-1303 / (858) 499-1304

<http://www.EMSL.com> / sandiegolab@emsl.com

EMSL Order: 431903661
Customer ID: WEST60
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
13 431903661-0013	PROJECT SAFE RELO - P1 INT. - CARPET GLUE	Gray/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
14 431903661-0014	PROJECT SAFE RELO - P1 INT. - CARPET GLUE	Gray/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
15 431903661-0015	PROJECT SAFE RELO - P2 INT. - CARPET GLUE	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16 431903661-0016	PROJECT SAFE RELO - P1 INT. - CB M	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
17 431903661-0017	PROJECT SAFE RELO - P2 INT. - CB M	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
18 431903661-0018	PROJECT SAFE RELO - P2 INT. - CB M	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19 431903661-0019	PROJECT SAFE RELO - P2 INT. - CELOTEX WALL	Tan Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
20 431903661-0020	PROJECT SAFE RELO - P1 INT. - DW WALL CORE	White Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
21 431903661-0021	PROJECT SAFE RELO - P1 INT. - DW WALL CORE	White Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
22 431903661-0022	PROJECT SAFE RELO - P2 INT. - DW WALL CORE	White Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
23 431903661-0023	PROJECT SAFE RELO - P1 INT. - 2x4 FIBERGLASS 2x4 CT	White/Yellow Fibrous Homogeneous	90% Glass	10% Non-fibrous (Other)	None Detected
24 431903661-0024	PROJECT SAFE RELO - P2 INT. - 2x4 FIBERGLASS 2x4 CT	White/Yellow Fibrous Homogeneous	90% Glass	10% Non-fibrous (Other)	None Detected
25 431903661-0025	OLD ADMIN - ROOF E - ROOF PEN M	Black Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
26 431903661-0026	OLD ADMIN - ROOF C - ROOF PEN M	Black Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
27 431903661-0027	OLD ADMIN - ROOF W - ROOF PEN M	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
28 431903661-0028	OLD ADMIN - ROOF N - ROOF EDGE M	White/Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
29 431903661-0029	OLD ADMIN - ROOF W - ROOF EDGE M	White/Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
30 431903661-0030	OLD ADMIN - ROOF E - ROOF CORE	Black Fibrous Homogeneous	6% Glass	94% Non-fibrous (Other)	None Detected
31-Roofing 431903661-0031	OLD ADMIN - ROOF W - ROOF CORE	Black Fibrous Homogeneous	6% Glass	94% Non-fibrous (Other)	None Detected

Initial report from: 05/01/2019 23:20:01



EMSL Analytical, Inc.

7916 Convoy Court, Building 4, Suite A San Diego, CA 92111

Tel/Fax: (858) 499-1303 / (858) 499-1304

<http://www.EMSL.com> / sandiegolab@emsl.com

EMSL Order: 431903661
Customer ID: WEST60
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
31-Paper 431903661-0031A	OLD ADMIN - ROOF W - ROOF CORE	Peach Non-Fibrous Homogeneous	70% Cellulose	30% Non-fibrous (Other)	None Detected
32-Finish Coat 431903661-0032	OLD ADMIN - EXT. WALKWAY E - CEILING STUCCO CORE	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
32-Base Coat 431903661-0032A	OLD ADMIN - EXT. WALKWAY E - CEILING STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
33-Finish Coat 431903661-0033	OLD ADMIN - EXT. WALKWAY C - CEILING STUCCO CORE	Green Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
33-Base Coat 431903661-0033A	OLD ADMIN - EXT. WALKWAY C - CEILING STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
34-Finish Coat 431903661-0034	OLD ADMIN - EXT. WALKWAY W - CEILING STUCCO CORE	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
34-Base Coat 431903661-0034A	OLD ADMIN - EXT. WALKWAY W - CEILING STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
35-Finish Coat 431903661-0035	OLD ADMIN - EXT WALL S - WALL STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
35-Base Coat 431903661-0035A	OLD ADMIN - EXT WALL S - WALL STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
36-Finish Coat 1 431903661-0036 <i>Two finish coat materials in sample were inseparable.</i>	OLD ADMIN - EXT WALL E - WALL STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
36-Finish Coat 2 431903661-0036A	OLD ADMIN - EXT WALL E - WALL STUCCO CORE	White/Green Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	<1% Chrysotile
36-Base Coat 431903661-0036B	OLD ADMIN - EXT WALL E - WALL STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
37-Finish Coat 431903661-0037	OLD ADMIN - EXT WALL N - WALL STUCCO CORE	White/Green Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	<1% Chrysotile
37-Base Coat 431903661-0037A	OLD ADMIN - EXT WALL N - WALL STUCCO CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
38-Cove Base 431903661-0038	OLD ADMIN - INT. NE - CB M	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
38-Mastic 431903661-0038A	OLD ADMIN - INT. NE - CB M	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
39-Cove Base 431903661-0039	OLD ADMIN - INT. S - CB M	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 05/01/2019 23:20:01



EMSL Analytical, Inc.

7916 Convoy Court, Building 4, Suite A San Diego, CA 92111

Tel/Fax: (858) 499-1303 / (858) 499-1304

<http://www.EMSL.com> / sandiegolab@emsl.com

EMSL Order: 431903661
Customer ID: WEST60
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
39-Mastic 431903661-0039A	OLD ADMIN - INT. S - CB M	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
40-Cove Base 431903661-0040	OLD ADMIN - INT. CNTR - CB M	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
40-Mastic 431903661-0040A	OLD ADMIN - INT. CNTR - CB M	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
41-Floor Tile 431903661-0041	OLD ADMIN - INT. RESTROOM - 9x9 FLOOR TILE & M	Beige Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
41-Mastic 431903661-0041A	OLD ADMIN - INT. RESTROOM - 9x9 FLOOR TILE & M	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
42-Floor Tile 431903661-0042	OLD ADMIN - INT. RESTROOM - 9x9 FLOOR TILE & M	Beige Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
42-Mastic 431903661-0042A	OLD ADMIN - INT. RESTROOM - 9x9 FLOOR TILE & M	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
43-Floor Tile 431903661-0043	OLD ADMIN - INT. CLOSET - 9x9 FLOOR TILE & M	Beige Non-Fibrous Homogeneous		96% Non-fibrous (Other)	4% Chrysotile
43-Mastic 431903661-0043A	OLD ADMIN - INT. CLOSET - 9x9 FLOOR TILE & M	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
44 431903661-0044	OLD ADMIN - INT. W - 2x4 CEILING TILE	White Fibrous Homogeneous	35% Cellulose 15% Min. Wool	10% Perlite 40% Non-fibrous (Other)	None Detected
45 431903661-0045	OLD ADMIN - INT. CNTR - 2x4 CEILING TILE	White Fibrous Homogeneous	35% Cellulose 15% Min. Wool	10% Perlite 40% Non-fibrous (Other)	None Detected
46 431903661-0046	OLD ADMIN - INT. NE - 2x4 CEILING TILE	White Fibrous Homogeneous	35% Cellulose 15% Min. Wool	10% Perlite 40% Non-fibrous (Other)	None Detected
47 431903661-0047	OLD ADMIN - INT. N - 12x12 CEILING TILE	White/Orange Non-Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
48 431903661-0048	OLD ADMIN - INT. W - 12x12 CEILING TILE	White/Orange Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
49 431903661-0049	OLD ADMIN - INT. W - 12x12 CEILING TILE	White/Orange Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
50-Skim Coat 431903661-0050	OLD ADMIN - INT. W. CLOSET - WALL PLASTER CORE	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
50-Plaster 431903661-0050A	OLD ADMIN - INT. W. CLOSET - WALL PLASTER CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
51-Skim Coat 431903661-0051	OLD ADMIN - INT. RESTROOM - WALL PLASTER CORE	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
51-Plaster 431903661-0051A	OLD ADMIN - INT. RESTROOM - WALL PLASTER CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 05/01/2019 23:20:01



EMSL Analytical, Inc.

7916 Convoy Court, Building 4, Suite A San Diego, CA 92111

Tel/Fax: (858) 499-1303 / (858) 499-1304

<http://www.EMSL.com> / sandiegolab@emsl.com

EMSL Order: 431903661

Customer ID: WEST60

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
52 431903661-0052	OLD ADMIN - INT. E - WALL PLASTER CORE	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
53-Texture 431903661-0053	OLD ADMIN - INT. S - WALL PLASTER CORE	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
53-Skim Coat 431903661-0053A	OLD ADMIN - INT. S - WALL PLASTER CORE	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
54 431903661-0054	OLD ADMIN - OUTROOM - 24x24 WALL TILE	White Fibrous Homogeneous	30% Cellulose 40% Min. Wool	30% Non-fibrous (Other)	None Detected
55 431903661-0055	OLD ADMIN - OUTROOM - WALL TILE GLUE	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
56 431903661-0056	OLD ADMIN - OUTROOM - 24x24 WALL TILE	White Fibrous Homogeneous	30% Cellulose 40% Min. Wool	30% Non-fibrous (Other)	None Detected
57 431903661-0057	OLD ADMIN - OUTROOM - WALL TILE GLUE	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
58 431903661-0058	OLD ADMIN - REAR OLD MECH. RM - HVAC DUCT TAPE	Black Fibrous Homogeneous	60% Glass	40% Non-fibrous (Other)	None Detected
59-Silver Paint 431903661-0059	OLD ADMIN - REAR OLD MECH. RM - HVAC DUCT TAPE	Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
59-Wrap 431903661-0059A	OLD ADMIN - REAR OLD MECH. RM - HVAC DUCT TAPE	White Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
60-Silver Paint 431903661-0060	OLD ADMIN - REAR OLD MECH. RM - HVAC DUCT TAPE	Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
60-Wrap 431903661-0060A	OLD ADMIN - REAR OLD MECH. RM - HVAC DUCT TAPE	White Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
61 431903661-0061	OLD ADMIN - REAR OLD MECH. RM - WALL TILE M	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
62 431903661-0062	OLD ADMIN - REAR OLD MECH. RM - WALL TILE M	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
63 431903661-0063	OLD ADMIN - REAR OLD MECH. RM - WALL TILE M	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
64-Mastic 431903661-0064	OLD ADMIN - REAR OLD MECH. RM - BLACK WALL M ON PLASTER	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
64-Skim Coat 431903661-0064A	OLD ADMIN - REAR OLD MECH. RM - BLACK WALL M ON PLASTER	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
64-Plaster 431903661-0064B	OLD ADMIN - REAR OLD MECH. RM - BLACK WALL M ON PLASTER	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 05/01/2019 23:20:01



EMSL Analytical, Inc.

7916 Convoy Court, Building 4, Suite A San Diego, CA 92111

Tel/Fax: (858) 499-1303 / (858) 499-1304

<http://www.EMSL.com> / sandiegolab@emsl.com

EMSL Order: 431903661
Customer ID: WEST60
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
65-Mastic 431903661-0065	OLD ADMIN - REAR OLD MECH. RM - BLACK WALL M ON PLASTER	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
65-Skim Coat 431903661-0065A	OLD ADMIN - REAR OLD MECH. RM - BLACK WALL M ON PLASTER	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
65-Plaster 431903661-0065B	OLD ADMIN - REAR OLD MECH. RM - BLACK WALL M ON PLASTER	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
66 431903661-0066	OLD ADMIN - REAR OLD MECH. RM - 12x12 WALL TILE	Tan/White Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
67-Drywall 431903661-0067	OLD ADMIN - REAR OLD MECH. RM - DW CEILING CORE	White Fibrous Homogeneous	2% Cellulose 2% Glass	96% Non-fibrous (Other)	None Detected
67-Joint Compound 431903661-0067A	OLD ADMIN - REAR OLD MECH. RM - DW CEILING CORE	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
68-Drywall 431903661-0068	OLD ADMIN - REAR OLD MECH. RM - DW CEILING CORE	White Fibrous Homogeneous	2% Cellulose 2% Glass	96% Non-fibrous (Other)	None Detected
68-Joint Compound 431903661-0068A	OLD ADMIN - REAR OLD MECH. RM - DW CEILING CORE	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
69-Drywall 431903661-0069	OLD ADMIN - REAR OLD MECH. RM - DW CEILING CORE	White Fibrous Homogeneous	2% Cellulose 2% Glass	96% Non-fibrous (Other)	None Detected
69-Joint Compound 431903661-0069A	OLD ADMIN - REAR OLD MECH. RM - DW CEILING CORE	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
70 431903661-0070	PROJECT SAFE RELO - P-1 EXT FRONT - WOOD TRIM WINDOW CAULK	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
71 431903661-0071	PROJECT SAFE RELO - P-2 EXT FRONT - WOOD TRIM WINDOW CAULK	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Analyst(s)

Alberto Guerrero (34)

Natalia Toscano (64)

Mariah Curran, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. San Diego, CA NVLAP Lab Code 200855-0, CA ELAP 2713, HI L-09-03

Initial report from: 05/01/2019 23:20:01

Special Project Name: _____

#431903661

Asbestos Bulk Sampling - Chain of Custody

WEST ILLC 7676 Hazard Center Dr. Suite 500 San Diego, CA 92115 Tel: 858.271.1842 Tel: 858.271.1856	Project Name: SYCAMORE E.S.	Contact: David A. Christy (619) 571-3987	Laboratory to be used: EMSL Analytical
	Project Location: SANTEE, CA.	Fax Results: (858) 271-1856	City/State: San Diego, California

Turn Around Time: ~~5 DAY~~ 10 ~~DAY~~ * verbals via David

Relinquished By: (sign / print)	Company	Date / Time	Received By: (sign / print)	Date / Time
David Christy / <i>David Christy</i>	WEST	4/17/19	<i>Riva Aguiar</i>	4/17/19 10:40 am

Sample #	Date	Area	Sample Location	Sample Description	Analysis Requested
01	4/16/19	PROJECT SAFE REID	P-2 Roof	METAL ROOF SAM	Asbestos - PLM
02			P1-P2 Roof	↓ ↓	Asbestos - PLM
03			P1 Roof	↓ ↓	Asbestos - PLM
04			P1-P2 EXT. S	RUBBER BASE @ CONCRETE	Asbestos - PLM
05			M	↓ ↓	Asbestos - PLM
06			N	↓ ↓	Asbestos - PLM
07			P1-P2 EXT. S	CONCRETE SLAB	Asbestos - PLM
08			M	↓ ↓	Asbestos - PLM
09			N	↓ ↓	Asbestos - PLM
10			P1 INT.	Sheet Floor Core	Asbestos - PLM
11			P1	↓ ↓	Asbestos - PLM
12			P2	↓ ↓	Asbestos - PLM
13			P1	Carpet Glue	Asbestos - PLM
14			P1	↓ ↓	Asbestos - PLM
15			P2	↓ ↓	Asbestos - PLM
16			P1	Core BASE MASTIC	Asbestos - PLM
17			P2	↓ ↓	Asbestos - PLM
18			P2	↓ ↓	Asbestos - PLM
19			P2	Celotex Wall	Asbestos - PLM
20			P1	drywall wall core	Asbestos - PLM
21			P1	↓ ↓	Asbestos - PLM
22			P2	↓ ↓	Asbestos - PLM
23			P1	2x4 FIBER GLASS 2x4	Asbestos - PLM
24			P2	↓ ↓	Asbestos - PLM

Special Project Name: _____

#431903661

Asbestos Bulk Sampling - Chain of Custody

WEST LLC 7676 Hazard Center Dr. Suite 500 San Diego, CA 92115 Tel: 858.271.1842 Tel: 858.271.1856	Project Name: <i>SYCAMORE E.S.</i>	Contact: David A. Christy (619) 571-3987	Laboratory to be used: EMSL Analytical
	Project Location: <i>Santee, CA.</i>	Fax Results: (858) 271-1856	City/State: San Diego, California

Turn Around Time: *5 DAY*

Relinquished By: (sign / print)	Company	Date / Time	Received By: (sign / print)	Date / Time
<i>David Christy</i>	WEST	<i>4/16/19</i>		

Sample #	Date	Area	Sample Location	Sample Description	Analysis Requested	
25	4/16/19	OLD Admin	Roof E	Roof Pen. MASTIC	Asbestos - PLM	
26	↓	↓	C	↓ ↓	Asbestos - PLM	
27			W	↓ ↓	Asbestos - PLM	
28			N	Roof EDGE MASTIC	Asbestos - PLM	
29			W	↓ ↓	Asbestos - PLM	
30			E	Roof CORE	Asbestos - PLM	
31			W	Roof CORE	Asbestos - PLM	
32			E	EXT. WALKWAY	Ceiling STUCCO CORE	Asbestos - PLM
33			C	↓ ↓	Asbestos - PLM	
34			W	↓ ↓	Asbestos - PLM	
35			S	EXT WALL	WALL STUCCO CORE	Asbestos - PLM
36			E	↓ ↓	Asbestos - PLM	
37			N	↓ ↓	Asbestos - PLM	
38			INT. NE	Cove BASE & MASTIC	Asbestos - PLM	
39			S.	↓ ↓	Asbestos - PLM	
40			Center	↓ ↓	Asbestos - PLM	
41			Restroom	9x9 Floor Tile & MASTIC	Asbestos - PLM	
42			Restroom	↓ ↓	Asbestos - PLM	
43			Closet	↓ ↓	Asbestos - PLM	
44	West	2x4 Ceiling Tile	Asbestos - PLM			
45	Center	↓ ↓	Asbestos - PLM			
46	N.E.	↓ ↓	Asbestos - PLM			
47	N	12x12 Ceiling Tile	Asbestos - PLM			
48	W	↓ ↓	Asbestos - PLM			

Print

Special Project Name: _____

#431903661

Asbestos Bulk Sampling - Chain of Custody

WEST LLC 7676 Hazard Center Dr. Suite 500 San Diego, CA 92115 Tel: 858.271.1842 Tel: 858.271.1856	Project Name: <i>SYCAMORE ES.</i>	Contact: David A. Christy (619) 571-3987 Fax Results: (858) 271-1856	Laboratory to be used: EMSL Analytical City/State: San Diego, California
	Project Location: <i>SANTEC CA.</i>		

Turn Around Time: *5 DAY*

Relinquished By: (sign / print)	Company	Date / Time	Received By: (sign / print)	Date / Time
<i>David Christy</i>	WEST			

Sample #	Date	Area	Sample Location	Sample Description	Analysis Requested
49	4-16-19 4/16/19	ADMIN OLD ADMIN	INT. WEST	12x12 ceiling tile	Asbestos - PLM (PIN)
50	4/16/19		INT. WEST CLOSET	WALL PLASTER CORE	Asbestos - PLM
51			RESTROOM		Asbestos - PLM
52			EAST		Asbestos - PLM
53			SOUTH		Asbestos - PLM
54			OUT ROOM	24x24 WALL TILE	Asbestos - PLM
55				WALL TILE GLUE	Asbestos - PLM
56				24x24 WALL TILE	Asbestos - PLM
57				WALL TILE GLUE	Asbestos - PLM
58			Rem old Mech. Rm.	HVAC DUCT TAPE	Asbestos - PLM
59					Asbestos - PLM
60					Asbestos - PLM
61				WALL TILE MASTIC	Asbestos - PLM
62					Asbestos - PLM
63					Asbestos - PLM
64				BLACK WALL MASTIC ON PLASTER	Asbestos - PLM
65					Asbestos - PLM
66				12x12 WALL TILE	Asbestos - PLM
67				DRYWALL CEILING CORE	Asbestos - PLM
68					Asbestos - PLM
69					Asbestos - PLM
70		PROJECT SAFE Rm	P1 EXT FRONT	Wood TRIM Window	Asbestos - PLM
71			P2 EXT FRONT		Asbestos - PLM
					Asbestos - PLM



WESTERN ENVIRONMENTAL & SAFETY TECHNOLOGIES LLC

“an environmental consulting firm”

Attachment Two - Lead Paint Inspection Report

Professional Environmental Consulting
and Training
Asbestos
Lead
Mold/Healthy Homes



Working for a clean environment
1101 California Ave, Suite 100
Corona, CA 92881
(951) 273-3410
info@allstate-services.com
www.allstate-services.com

April 18, 2019

Western Environmental & Safety Tech.
Mr. David Christy
7966 Arjons Drive, Suite 110
San Diego, CA 92126

RE: Lead-based paint testing at Sycamore Canyon School, 10201 Settle Road, Santee,
California 92071

Dear Mr. David Christy:

In accordance with your request and authorization, Allstate Services conducted lead-based paint testing at Sycamore Canyon School located at 10201 Settle Road in Santee, California on April 16, 2019. Please note that only selected areas of the Project Safe Building, Old Admin Building, and Building 6-8 to K1-K2 were tested for lead-based paint at this time.

The on-site work was performed by Stacey J. Milano, California Certified Lead Inspector/Assessor # 315 using an XRF Analyzer following all required protocols.

Lead-based paint was not identified on the selected surfaces tested at the above-mentioned property. Please see the attached Detailed XRF Testing Results for further details.

If you need any further assistance after reviewing your report, please do not hesitate to contact me. Allstate Services remains available to assist you in anyway possible.

Sincerely,

A handwritten signature in blue ink that reads "Stacey J. Milano".

Stacey J. Milano
CDPH Inspector/Assessor #315

Attachments: Detailed XRF Testing Results, Calibration Log, Inspector Certification Copy, 8552 Form

DETAILED XRF TESTING RESULTS

Sycamore Canyon School - Project Safe Building
10201 Settle Road, Santee, California 92071

Sample	Area	Room Equivalent	Side Tested	Component	Substrate	Color	Condition	Lead (mg/cm ²)	Results	Quantities For Entire Area	Comments
1	Exterior	Project Safe Building	A	Wall	Plaster	Beige	Intact	0.0	Negative		
2	Exterior	Project Safe Building	B	Wall	Plaster	Beige	Intact	0.2	Negative		
3	Exterior	Project Safe Building	C	Wall	Plaster	Beige	Intact	0.0	Negative		
4	Exterior	Project Safe Building	D	Wall	Plaster	Beige	Intact	0.3	Negative		
5	Exterior	Project Safe Building	A	Upper Trim	Metal	Blue	Intact	0.3	Negative		
6	Exterior	Project Safe Building	A	Door	Wood	Blue	Intact	0.2	Negative		
7	Exterior	Project Safe Building	A	Door Frame	Plaster	Beige	Intact	0.1	Negative		
8	Exterior	Project Safe Building	A	Window Frame	Plaster	Beige	Intact	0.1	Negative		
9	Exterior	Project Safe Building	B	Corner Trim	Plaster	Beige	Intact	0.0	Negative		
10	Interior	PS1	A	Wall	Drywall	White	Intact	0.0	Negative		
11	Interior	PS1	B	Wall	Drywall	White	Intact	0.0	Negative		
12	Interior	PS1	C	Wall	Drywall	White	Intact	0.0	Negative		
13	Interior	PS1	D	Wall	Drywall	White	Intact	0.1	Negative		
14	Interior	PS1	A	Door	Metal	Blue	Intact	0.2	Negative		
15	Interior	PS1	A	Door Frame	Metal	Blue	Intact	0.0	Negative		
16	Interior	PS1	C	Window Frame	Wood	White	Intact	0.0	Negative		
17	Interior	PS2	A	Wall	Drywall	White	Intact	0.3	Negative		
18	Interior	PS2	B	Wall	Drywall	White	Intact	0.0	Negative		
19	Interior	PS2	C	Wall	Drywall	White	Intact	0.0	Negative		
20	Interior	PS2	D	Wall	Drywall	White	Intact	0.0	Negative		
21	Interior	PS2	A	Door	Metal	Blue	Intact	0.2	Negative		
22	Interior	PS2	A	Door Frame	Metal	Blue	Intact	0.2	Negative		
23	Interior	PS2	C	Window Frame	Wood	White	Intact	0.0	Negative		

DETAILED XRF TESTING RESULTS

Sycamore Canyon School - Old Admin Building
10201 Settle Road, Santee, California 92071

Sample	Area	Room Equivalent	Side Tested	Component	Substrate	Color	Condition	Lead (mg/cm ²)	Results	Quantities For Entire Area	Comments
24	Exterior	Old Admin Bldg. to Bldg. 6-8	---	Ceiling	Stucco	Beige	Intact	0.2	Negative		
25	Exterior	Old Admin Bldg. to Bldg. 6-8	A	Flashing	Metal	White	Intact	0.0	Negative		
26	Exterior	Old Admin Bldg. to Bldg. 6-8	A	Post	Metal	Blue	Intact	0.4	Negative		
27	Exterior	Old Admin Building	A	Wall	Stucco	Beige	Intact	0.2	Negative		
28	Exterior	Old Admin Building	B	Wall	Stucco	Beige	Intact	0.1	Negative		
29	Exterior	Old Admin Building	C	Wall	Stucco	Beige	Intact	0.1	Negative		
30	Exterior	Old Admin Building	D	Wall	Stucco	Beige	Intact	0.3	Negative		
31	Exterior	Old Admin Building	A	Door	Metal	Blue	Intact	0.2	Negative		
32	Exterior	Old Admin Building	A	Door Frame	Wood	Blue	Deteriorated	0.2	Negative		
33	Exterior	Old Admin Building	D	Window Frame	Wood	Blue	Intact	0.3	Negative		
34	Exterior	Old Admin Building	D	Door	Wood	Blue	Intact	0.4	Negative		
35	Exterior	Old Admin Building	C	Vent	Metal	Beige	Intact	0.0	Negative		
36	Exterior	Old Admin Building	C	Flashing	Metal	Beige	Deteriorated	0.1	Negative		
37	Interior	Art Studio	A	Wall	Plaster	Gray	Intact	0.2	Negative		
38	Interior	Art Studio	B	Wall	Plaster	Gray	Intact	0.2	Negative		
39	Interior	Art Studio	C	Wall	Plaster	Gray	Intact	0.2	Negative		
40	Interior	Art Studio	D	Wall	Plaster	Gray	Intact	0.1	Negative		
41	Interior	Art Studio	B	Door	Wood	Brown	Intact	0.2	Negative		
42	Interior	Art Studio	B	Door Frame	Wood	White	Intact	0.3	Negative		
43	Interior	Art Studio	A	Door	Metal	Blue	Intact	0.2	Negative		
44	Interior	Art Studio	A	Door Frame	Wood	Blue	Deteriorated	0.3	Negative		
45	Interior	Art Studio	A	Window Frame	Wood	White	Intact	0.3	Negative		
46	Interior	Art Studio	D	Lower Cabinet	Wood	Multicolor	Intact	0.0	Negative		
47	Interior	Art Storage	A	Wall	Plaster	White	Intact	0.0	Negative		
48	Interior	Art Storage	B	Wall	Plaster	White	Intact	0.2	Negative		
49	Interior	Art Storage	C	Wall	Plaster	White	Intact	0.0	Negative		
50	Interior	Art Storage	D	Wall	Plaster	White	Intact	0.3	Negative		
51	Interior	Art Storage	A	Door	Wood	Brown	Intact	0.1	Negative		
52	Interior	Art Storage	A	Door Frame	Wood	White	Intact	0.1	Negative		
53	Interior	Art Storage	B	Door	Wood	White	Intact	0.3	Negative		
54	Interior	Art Storage	C	Window Frame	Wood	White	Intact	0.0	Negative		
55	Interior	Book Room	A	Wall	Plaster	White	Intact	0.0	Negative		
56	Interior	Book Room	B	Wall	Plaster	White	Intact	0.0	Negative		
57	Interior	Book Room	C	Wall	Plaster	White	Intact	0.0	Negative		
58	Interior	Book Room	D	Wall	Plaster	White	Intact	0.1	Negative		
59	Interior	Book Room	A	Door	Wood	Brown	Intact	0.0	Negative		
60	Interior	Book Room	A	Door Frame	Wood	White	Intact	0.3	Negative		
61	Interior	Work Room	A	Wall	Plaster	Beige	Intact	0.0	Negative		
62	Interior	Work Room	B	Wall	Plaster	Beige	Intact	0.2	Negative		
63	Interior	Work Room	C	Wall	Plaster	Green	Intact	0.3	Negative		
64	Interior	Work Room	D	Wall	Plaster	Beige	Intact	0.1	Negative		
65	Interior	Work Room	A	Door	Metal	Blue	Intact	0.1	Negative		
66	Interior	Work Room	A	Door Frame	Wood	Blue	Intact	0.2	Negative		

DETAILED XRF TESTING RESULTS

Sycamore Canyon School - Old Admin Building
10201 Settle Road, Santee, California 92071

Sample	Area	Room Equivalent	Side Tested	Component	Substrate	Color	Condition	Lead (mg/cm ²)	Results	Quantities For Entire Area	Comments
67	Interior	Work Room	B	Door	Wood	White	Intact	0.1	Negative		
68	Interior	Work Room	D	Window Frame	Wood	Green	Intact	0.0	Negative		
69	Interior	Work Room	A	Upper Cabinet	Wood	White	Intact	0.0	Negative		
70	Interior	Work Room	A	Lower Cabinet	Wood	Green	Intact	0.3	Negative		
71	Interior	Office	A	Upper Wall	Plaster	Pink	Intact	0.0	Negative		
72	Interior	Office	B	Wall Panel	Wood	Brown	Intact	0.0	Negative		
73	Interior	Office	C	Wall Panel	Wood	Brown	Intact	0.0	Negative		
74	Interior	Office	D	Upper Wall	Plaster	Pink	Intact	0.0	Negative		
75	Interior	Office	D	Baseboard	Wood	Brown	Intact	0.0	Negative		
76	Interior	Office	D	Door	Wood	Brown	Intact	0.0	Negative		
77	Interior	Office	D	Door Frame	Wood	Pink	Deteriorated	0.2	Negative		
78	Interior	Restroom	A	Wall	Plaster	Beige	Intact	0.1	Negative		
79	Interior	Restroom	B	Wall	Plaster	Beige	Intact	0.0	Negative		
80	Interior	Restroom	C	Wall	Plaster	Beige	Intact	0.1	Negative		
81	Interior	Restroom	D	Wall	Plaster	Beige	Intact	0.0	Negative		
82	Interior	Restroom	A	Baseboard	Wood	Beige	Deteriorated	0.3	Negative		
83	Interior	Restroom	D	Door	Wood	Beige	Deteriorated	0.0	Negative		
84	Interior	Restroom	D	Door Frame	Wood	Beige	Deteriorated	0.2	Negative		
85	Interior	Restroom	---	Ceiling	Plaster	Beige	Intact	0.0	Negative		
86	Interior	Copier Office	A	Wall	Plaster	Beige	Deteriorated	0.0	Negative		
87	Interior	Copier Office	B	Wall	Plaster	Beige	Deteriorated	0.1	Negative		
88	Interior	Copier Office	C	Wall	Plaster	Beige	Deteriorated	0.1	Negative		
89	Interior	Copier Office	D	Wall	Plaster	Beige	Deteriorated	0.1	Negative		
90	Interior	Copier Office	A	Door	Metal	Blue	Intact	0.2	Negative		
91	Interior	Copier Office	A	Door Frame	Wood	Blue	Deteriorated	0.2	Negative		
92	Interior	Storage 1	A	Wall	Plaster	Beige	Intact	0.0	Negative		
93	Interior	Storage 1	B	Wall	Plaster	Beige	Intact	0.2	Negative		
94	Interior	Storage 1	C	Wall	Plaster	Beige	Intact	0.2	Negative		
95	Interior	Storage 1	D	Wall	Plaster	Beige	Intact	0.1	Negative		
96	Interior	Storage 1	B	Door	Metal	Blue	Intact	0.2	Negative		
97	Interior	Storage 1	B	Door Frame	Wood	Blue	Deteriorated	0.2	Negative		
98	Interior	Storage 2	A	Wall	Plaster	Beige	Intact	0.0	Negative		
99	Interior	Storage 2	B	Wall	Plaster	Beige	Deteriorated	0.1	Negative		
100	Interior	Storage 2	C	Wall	Plaster	Beige	Intact	0.0	Negative		
101	Interior	Storage 2	D	Wall	Plaster	Beige	Intact	0.0	Negative		
102	Interior	Storage 2	B	Baseboard	Wood	Brown	Intact	0.2	Negative		
103	Interior	Storage 2	B	Door	Metal	Blue	Intact	0.0	Negative		
104	Interior	Storage 2	B	Door Frame	Wood	Blue	Deteriorated	0.3	Negative		
105	Interior	Storage 2	---	Ceiling	Plaster	White	Intact	0.3	Negative		
106	Interior	Table Storage Room	A	Wall	Plaster	White	Deteriorated	0.0	Negative		
107	Interior	Table Storage Room	B	Wall	Plaster	White	Deteriorated	0.2	Negative		
108	Interior	Table Storage Room	C	Wall	Plaster	White	Deteriorated	0.0	Negative		
109	Interior	Table Storage Room	D	Wall	Plaster	White	Deteriorated	0.3	Negative		

DETAILED XRF TESTING RESULTS

Sycamore Canyon School - Old Admin Building
10201 Settle Road, Santee, California 92071

Sample	Area	Room Equivalent	Side Tested	Component	Substrate	Color	Condition	Lead (mg/cm ²)	Results	Quantities For Entire Area	Comments
110	Interior	Table Storage Room	D	Baseboard	Wood	Brown	Intact	0.1	Negative		
111	Interior	Table Storage Room	C	Door	Metal	Blue	Deteriorated	0.2	Negative		
112	Interior	Table Storage Room	C	Door Frame	Wood	Blue	Deteriorated	0.4	Negative		
113	Interior	Table Storage Room	---	Ceiling	Wood	White	Deteriorated	0.0	Negative		

DETAILED XRF TESTING RESULTS

Sycamore Canyon School - Building 6-8 to K1-K2
10201 Settle Road, Santee, California 92071

Sample	Area	Room Equivalent	Side Tested	Component	Substrate	Color	Condition	Lead (mg/cm ²)	Results	Quantities For Entire Area	Comments
114	Exterior	Building 6-8 to K1-K2	---	Ceiling	Stucco	Beige	Intact	0.3	Negative		
115	Exterior	Building 6-8 to K1-K2	B	Flashing	Metal	White	Intact	0.1	Negative		
116	Exterior	Building 6-8 to K1-K2	B	Post	Metal	Blue	Intact	0.3	Negative		

ALLSTATE SERVICES
XRF CALIBRATION FORM

Address: Sycamore Canyon School, 10201 Settle Road, Santee, California 92071

Device: RMD, LPA-1

Date: April 16, 2019

Inspector: Stacey J. Milano

Calibration Check Tolerance Used: 0.7 mg/cm² - 1.3 mg/cm² (Inclusive)
Use Level III (1.02 mg/cm²) NIST SRM Paint film

First Calibration Check

Time: 10:30 a.m.

1 st Reading	2 nd Reading	3 rd Reading	1 st Average
1.0	1.0	1.0	1.0

Second Calibration Check

Time: 11:55 a.m.

1 st Reading	2 nd Reading	3 rd Reading	2 nd Average
1.0	0.9	1.0	1.0

Third Calibration Check (If Needed)

Time:

1 st Reading	2 nd Reading	3 rd Reading	3 rd Average

State of California Department of Public Health

Lead-Related
Construction
Certificate

Certificate
Type

Expiration
Date



Inspector/Assessor	05/02/2019
Supervisor	05/02/2019
Project Designer	05/02/2019
Project Monitor	05/02/2019

Stacey J. Milano

ID #: 315

LEAD HAZARD EVALUATION REPORT

Section 1 – Date of Lead Hazard Evaluation _____

Section 2 – Type of Lead Hazard Evaluation (Check one box only)

Lead Inspection Risk assessment Clearance Inspection Other (specify) _____

Section 3 – Structure Where Lead Hazard Evaluation Was Conducted

Address [number, street, apartment (if applicable)]		City	County	Zip Code
Construction date (year) of structure	Type of structure <input type="checkbox"/> Multi-unit building <input type="checkbox"/> School or daycare <input type="checkbox"/> Single family dwelling <input type="checkbox"/> Other _____		Children living in structure? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Don't Know	

Section 4 – Owner of Structure (if business/agency, list contact person)

Name		Telephone number		
Address [number, street, apartment (if applicable)]		City	State	Zip Code

Section 5 – Results of Lead Hazard Evaluation (check all that apply)

No lead-based paint detected
 Intact lead-based paint detected
 Deteriorated lead-based paint detected
 No lead hazards detected
 Lead-contaminated dust found
 Lead-contaminated soil found
 Other _____

Section 6 – Individual Conducting Lead Hazard Evaluation

Name		Telephone number		
Address [number, street, apartment (if applicable)]		City	State	Zip Code
CDPH certification number	Signature <i>Stacey J. Milano</i>		Date	

Name and CDPH certification number of any other individuals conducting sampling or testing (if applicable)

Section 7 – Attachments

- A. A foundation diagram or sketch of the structure indicating the specific locations of each lead hazard or presence of lead-based paint;
- B. Each testing method, device, and sampling procedure used;
- C. All data collected, including quality control data, laboratory results, including laboratory name, address, and phone number.

First copy and attachments retained by inspector
 Second copy and attachments retained by owner

Third copy only (no attachments) mailed or faxed to:
 California Department of Public Health
 Childhood Lead Poisoning Prevention Branch Reports
 850 Marina Bay Parkway, Building P, Third Floor
 Richmond, CA 94804-6403
 Fax: (510) 620-5656